


VR-50HD MK II AUDIO BLOCK DIAGRAM

*In HDCP mode, no audio and video signals are output from these connectors.



VR-50HD MK II VIDEO BLOCK DIAGRAM

*In HDCP mode, no audio and video signals are output from these connectors.